

To: Williams, Mike[Mike.Williams@tetrattech.com]
From: McCoy, Erin
Sent: Fri 5/13/2016 11:31:16 AM
Subject: RE: Des Moines TCE, START Task 0144, ASR form

Mike, a couple of questions.

1. I don't see any MS/MSD or duplicate samples. Are they included in the numbers?
2. My intent was not to sample for asbestos, but to just determine if it was present. Can we do that without sampling?
3. The numbers don't make sense to me. Just as an example, I thought we had 40 sample locations for wipe samples, plus the duplicate and MS/MSD, but you have 38 listed.

Please let me know so I can turn this in asap today. Thanks!



Erin McCoy, P.G. | Remedial Project Manager

EPA Region 7 | Superfund Division | Iowa Nebraska Branch

11201 Renner Blvd | Lenexa, KS 66219

Phone: 913.551.7977

mccoy.erin@epa.gov | www.epa.gov

From: Williams, Mike [mailto:Mike.Williams@tetrattech.com]
Sent: Thursday, May 12, 2016 3:23 PM
To: McCoy, Erin <McCoy.Erin@epa.gov>
Cc: Simpson, John <John.Simpson@tetrattech.com>
Subject: Des Moines TCE, START Task 0144, ASR form

Erin:

Please find attached the ASR form for the Des Moines TCE project. The QAPP should be finished by tomorrow. If you have any questions, feel free to ask.

Best,

Mike

Mike Williams | Sr. Project Manager/Hydrogeologist

415 Oak Street | Kansas City, Missouri 64106 | www.tetratech.com
Direct: 816.412.1767 | Main: 816.412.1741 | Fax: 816.410.1748 | Mobile: 913.689.9367

Mike.Williams@tetratech.com

Tetra Tech | Complex World, Clear Solutions™

PLEASE NOTE: This message, including any attachments, may include privileged, confidential and/or inside information. Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.